

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020	District: Jammu
Division : Jammu	Length (km): 3.00 Km
Name of the Road: Sighiya To Bela Kharan Road	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N/19-20/Jammu-18	Road Id No.: 28411032619
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	SAU N/A
b)	Condition of Surfacing	SAU N/A
c)	Riding Quality	SAU N/A
d)	Road Camber	SAU N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Work not started

(Signature)
07/12/20

(Signature)

NAME:

DESIGNATION:

(Ashok Kumar Anja.)
AE, R&D, Laxmipur