FIELD INSPECTION REPORT

te of In	0 1 2 20 20	trict: Tameu'	
ivision: Ignw		Length (km): 3.10 KM	
me of t	the Road: Mahader Simadia		
	Programme: MAINTENANCE		
		ad Id No.: 284110326	529
	the Project: Ongoing/Completed/Unc		
	a case of: New Connectivity/Up gr	hecked in the same	
l. No.	[2] [2] [2] [2] [3] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	neckeo	Remarks
1.	Pavement		
a)	Road Junction condition		√S/U
b)	Condition of Surfacing		√8/ U
c)	Riding Quality		√8/U
d)	Road Camber		√8/ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ハ
f)	Contraction Joints provided or not (CC Pavement)		Yes/No ∧/
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		and the same
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U W
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		-S/SRI/U N
c)	Condition of railings/slab/approach for	Bridges	S /SRI/U N
3.	Road Furniture	The state of the s	
a)	Whether sign boards/informatory/cau stones/Pavement road markings are pro-	ovided and maintained	Yes/No
1 2 4	Gompliance History		
a)	Status of ATR's & any others		NIA

Overall Rating

Satisfactory (S)	' S'
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	

NAME:

DESIGNATION: