

FIELD INSPECTION REPORT

Date of Inspection : 5.12.20	District: <u>Muzaffargarh</u>
Division : <u>Muzaffargarh</u>	Length (km): <u>500 KM</u>
Name of the Road: <u>Besni Raschery</u>	<u>KE</u> <u>Wahl No-14 NE Sui V Panchayat</u> <u>Partel KE</u>
Scheme/Programme: MAINTENANCE	<u>After new Kachhri</u>
Package No.: <u>MKN 19-20</u>	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	<u>NEW MAINTENANCE</u>

Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	NA S/U
b)	Condition of Surfacing	NA S/U
c)	Riding Quality	NA S/U
d)	Road Camber	NA S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	NA Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Brayesh Kumar

DESIGNATION: AE
Besni