

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020 District: Nalanda
 Division - Hilsa Length (km): 0.350 KM
 Name of the Road: MILK Narsingh Road TO KESHOPUR
 Scheme Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SRI
b)	Condition of Surfacing	SRI
c)	Riding Quality	SRI
d)	Road Camber	SRI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c)	Condition of railings/slab/approach for Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U)

IS WORK IS PROGRESS UNDER NEW MAINTENANCE
 Policy

TARUN KUMAR

NAME:

Tarun
 (Signature)