51. No-9

FIELD INSPECTION REPORT

Date of Inspection: 06-12-2020 Division: Parton			District: Samastipur Length (km):	
Name o	f the Road: Pa-	ton Station che	TWK to RWD Sadak N	a huzan
-	/Programme:	MAINTENANCE	the state of the s	
Package	No.:		Road Id No.:	
Status o	f the Project:	Ongoing/Completed	Under Maintenance Ongo	ing
Work is	a case of:	New Connectivity/U	p gradation/ Maintenance 🦯	AND DESCRIPTION OF THE PERSON ASSESSMENT OF STREET
Sl. No.	Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			
				a landa and a second

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work wot started.

NAME: Ajay kumar Singh

DESIGNATION:

06/0(2/2020 (Signature)