FIELD INSPECTION REPORT

Date of I	Inspection · 48	112/2020	District: Japonui	
Date of Inspection: 69/12/2020 Division: Jaguer			Length (km): 3.30 Km	
			a Charle Khirbhorne to I	umafusi
Scheme/	Programme:	MAINTENANCE	a Charle Khirbhogua to I Manyhi tola Kanas Se	anthal Tol
Package	No.: Ma-NI	10 - 2/10 -	Road Id No.: 284110335	38
Status of the Project: ()ngorng/Complet		()ngorng/Completed	VUILLE IVILLIANDE CONTRACTOR	
			Jp gradation/ Maintenance	Property and the second
Sl. No.			he checked	Remarks
1.	Pavement			
a)	Road Junction condition			-\$70
	Condition of Surfacing			-8/0
b)				SAU
c)	Riding Quality			SAU
d)	Road Camber			0.87.08
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Drain	ree Land		
	Condition of head walls in Hume pipe culverts including its painting			_S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC culverts			SISRIPU
b)	Condition of railings/slab/approach for Bridges			-8/SRI/U
c)	是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个			
3	Road Dornili		700	The state of the s
a)	Whether sign beards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance	History		
a)	Status of ATR's & any others			NA

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

July 20

(Signature)

NAME:

DESIGNATION:

Asheli Kunz Aya) AE, RND, Langinz