· In Tendel Process

Date of I	nspection:	05-12-2020	Dhtriet: Zemu	
Division: James			Length (km): 3 3 1cm	
	the Road: K	enulous Rocker	nous Rol to Cherpaso	m·
	Programme:	MAINTENANCE		-0
THE RESERVE OF THE PERSON NAMED IN	the state of the s	1-19-70/Jam-31	Road Id No.: 284-110 33	587
Status of the Project: Ongoing/Complete Work is a case of: New Connectivity.		New Connectivity/	/Up gradation/ Maintenance	
Sl. No.		Parameters to		Remarks
1.	Pavement		There is an an analysis of the second	
a)	Road Junction condition			
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drain:	ige	The day	
a)	Condition of	S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance	History Establish		
a)	the state of the s	R's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

carps teles

Executive Engineer RWD Wo(RigDHMSR)n, Jamui

NAME: