In Tonder process

FIELD INSPECTION REPORT

Date of Inspection :		Dh	District: James	
Division: Jamui		Lei Lei	Length (km): 2.00 km	
			how. road	
Scheme/Programme:		MAINTENANCE		
Package No.: Status of the Project:		MR-39nui-24 Road Id No.: 284110 33598 Ongoing/Completed/Under Maintenance		
	a case of:	New Connectivity/Up gra		
Sl. No.	The state of the s	Parameters to be cl		Remarks
	Pavement			Total
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Curniture			
a) ;	stones/Pavement road markings are provided and maintained			Yes/No
4,	Compliance I	istory		1
a)	Status of ATR			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	terbo is
Unsatisfactory (U)	

Executive Engineer
RWD Works Division, Jamui

NAME: