## FIELD INSPECTION REPORT

Date of Inspection: 07/12/2020 District: muzasfaspud					
Division: myzadarspur Earla -2			Length (km): 1 - 450 Km		
Name of the	Rond: Pa	hsaul to laicha	input		
Scheme/Pro		MAINTENANCE	MR 3054		
Package No	.:		Road Id No.:		
Status of th	-		/Under Maintenance		
***************************************			Jp gradation/ Maintenance	-	
Sl. No.		Parameters to	be checked	Remarks	
1. P	Pavement				
a) R	Road Junction condition			S/U	
b) C	Condition of Surfacing			S/U	
c) R	Riding Quality			S/U	
d) R	Road Camber			S/U	
e) W	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
The second secon	Contraction Joints provided or not (CC Pavement)			Yes/No	
g) C	Compaction of flank/slope & raincuts if any			Yes/No -	
	Cross Drainage				
a) (	Condition of head walls in Hume pipe culverts including its painting				
	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
	Condition of railings/slab/approach for Bridges			S/SRI/U	
3. F	Road Furnit	ure			
a) V	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4. (	Compliance History			E m	
a) S	Status of ATI	R's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This scheme is New MR3054 policy work is not started

(Signature)

NAME: Umesh Padway

DESIGNATION: 36