

## FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020		District: Banka
Division : Banka-1		Length (km): 1.87
Name of the Road: Bishnupur road - Pakaria		
Scheme/Programme: MAINTENANCE		
Package No.: RM/BA/BAN/20/0003		Road Id No.: 20703502070
Status of the Project: <input checked="" type="checkbox"/> Ongoing/ <input type="checkbox"/> Completed/ <input type="checkbox"/> Under Maintenance		
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/ <input checked="" type="checkbox"/> Up gradation/ <input type="checkbox"/> Maintenance		

  

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U ongoing
b)	Condition of Surfacing	S/U ongoing
c)	Riding Quality	S/U ongoing
d)	Road Camber	S/U ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No ongoing
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No ongoing
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	satisfactory (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pritam  
 05.12.2020  
 (Signature)

NAME: PRITAM KUMAR

DESIGNATION: A.E