

# FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	Banka
Division :	Banka-1	Length (km):	3
Name of the Road:	Chhatan to Khajuri		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/BA/BAN/19/0005	Road Id No.:	20703502217
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	✓ Satisfactory (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Pritham  
04.12.2020  
(Signature)

NAME: PRITHAM KUMAR

DESIGNATION: A.E