## FIELD INSPECTION REPORT

Date of	Inspection: 07/12/2020 Di	strict: T		
Didd-				
Name o	of the Road: Cyauhan Nahan to	·		-
Scheme	Programme: MAINTENANCE	Noudelly Koro		1
Packag	e No .: MR-N/19-20/MP/22 Ro	ad Id No.: 2080 4101	DD7	1
Status	of the Project: Ongoing/Completed/Unc	der Maintenance		. ,
Work is a case of: New Connectivity/Up gradation/ Maintenance				1
SI No.	Paramoters to be c	hecked	Remarks	Ĝ
	Patamoters to be c			
a)	Road Junction condition		S/U′	
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	on-goly
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N.	A
f)	Contraction Joints provided or not (CC Pavement)		Yes/No /	A
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	CroseDrainingc	A British and Berneute		
a)	Condition of head walls in Hume pipe culverts including its painting		S7SRI/U W	which as not been done
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts		-S/SRI/U	Mora
c)	Condition of railings/slab/approach for Bridges		.S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionstones/Pavement road markings are provided	Yes/No		
4.00	Complinite History			
a)	Status of ATR's & any others		MA	
Overall	Rating		N.A.	
Overall	Satisfactory (S)			
	Satisfactory but require	es Improvement (SRI)		
	Unsatisfactory (U)		7.0	

A.E

(Signature)

NAME:

**DESIGNATION:**