FIELD INSPECTION REPORT

	FIELD INSTECT			
Date of Inspection: 05/12/2020 District: Janu'				
		ength (km): 3.725KM		
	the Road: Manpur - Aux canda - 1	Road to Sundan Bandh	via Manpur	Bathan Mushari
	Programme: MAINTENANCE			
	No.: MR-N [19-21 Squw] 10 R the Project: Ongoing/Completed/Un	oad Id No.: 2080 4101	061	
	a case of: New Connectivity/Up g			
\$1. No.	Parameters to be		Remarks	
1	Pavement			
a)	Road Junction condition		S/U T	
b)	Condition of Surfacing		S/U	on-golar
c)	Riding Quality		S/U	on-going
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N	A
f)	Contraction Joints provided or not (CC Pavement)		Yes/No- N	A
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage	note that the		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	work has been not
b) '	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	Start
c)	Condition of railings/slab/approach for Bridges		S/SRI/UNI	
3.	Road Furniture	The Action of the Control of the Con		
a)	Whether sign boards/informatory/cau stones/Pavement road markings are pro	Yes/No		
4	Compliance History			
a)	Status of ATR's & any others		NIA	
Overall	Rating :	'A	JA.	
J . J. W. 1	Satisfactory (S)			
	Satisfactory but req	uires Improvement (SRI)		

Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME:

DESIGNATION: