FIELD INSPECTION REPORT

of Inspe	ction: 07/12/2020 District: Jamui	
sion: Jamus Length (km): 0.84 Km		(m)
e of the I		
eme/Prog	ramme: MAINTENANCE	
	MR-N/19-20 Jamui- 18 Road Id No.: 2080410	1068
us of the		
rk is a ca No.	Parameters to be checked	Remarks
i. Pa	vement	
a) Ro	oad Junction condition	_\$/\tau
b) Co	ondition of Surfacing	_SAJ-
	iding Quality	SAU
	oad Camber	SAU
u v	Whether free from defects such as visible cracks, exposing generates in case of CC Pavement.	Yes/No
f) C	Contraction Joints provided or not (CC Pavement)	_Yes/No
	Compaction of flank/slope & raincuts if any	Yes/No
	Pross Drainage	
	Condition of head walls in Hume pipe culverts including its paint	ing _ S/SRI/ U
	Condition of Abutment & Wing walls, Slab in RCC culverts	_S/SRI/U
/	Condition of railings/slab/approach for Bridges	_S/SRI/U
	Coad Egeniture	324
a) V	Whether sign boards/informatory/cautionary Board/km & 20 stones/Pavement road markings are provided and maintained	00m Yes/No
以, 告述(compliance History	81.05
	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

work not started.

07/12/20

(Signature)

NAME:

DESIGNATION:

Ashole Kumas Anger) AE, RWD, Laxmipur