FIELD INSPECTION REPORT

Date of	Inspection: 07/12/2020 D	Pistrict: James'	
		ength (km): 4.50 Km)
	fthe Road: Kafeuina - Nun	mbez Raad	
	Programme: MAINTENANCE		
ackage	e No .: mp-N/9-20 / Tanini - 7 R	oad Id No.: 208041020	91
otatus o	of the Project: Ongoing/Completed/Un	nder Maintenance	
Principal VI Child	s a case of: New Connectivity/Up g		AN AMPLICATION AND ADDRESS OF THE PARTY OF T
Sl. No.	公司的企业的企业,以外的企业的企业,以外的企业的企业的企业,不是不是一个企业的企业,不是一个企业的企业,不是一个企业的企业,不是一个企业的企业,不是一个企业的	clecked	Remarks
1	Pavement		
a)	Road Junction condition		- 8/U
b)	Condition of Surfacing		_S/U_
c)	Riding Quality		-S/U
d)	Road Camber		- S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No-
12	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture	W.	
a)	Whether sign boards/informatory/caut stones/Pavement road markings are provided	Yes/No	
	Compliance History		Committee of the Commit
a)	Status of ATR's & any others		N/A

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

work not starte

NAME:

DESIGNATION:

(Signature)

Ashak Kimon Aye,