FIELD INSPECTION REPORT

Date of I	nspection: (7/12/2020 District:	Janu'		
Division: Janey Length (km): 2.086 KM					
Name of		ring to Mandr			
	Programme:	MAINTENANCE			
Package No.: MR-N/1920/5944 108 Road Id No.: 2004/020				199	
Status of the Project: Ongoing/Completed/Under Maintenance					
	a case of:	New Connectivity/Up gradation	on/Maintenance		1
Sl. No.		Paramoters to be checke		Remarks	
1.	Pavement				
a)	Road Junction condition			S/U 🦳	
b)	Condition of Surfacing			S/U	- 1
c)	Riding Quality			S/U	m-going
d)	Road Camber			s/U J	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No N	IA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No A	//A
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U N	A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Firmilure				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	Compliance History				
a)	n a comp to 0			NIA	
				'N.A)	_
Overall	Rating :	Satisfactory (S)			
		Satisfactory but requires I	mprovement (SRI)		
		Ilmentiefactory (II)			1

, , , , , , , , , , , , , , , , , , ,

samb,

NAME:

DESIGNATION: