FIELD INSPECTION REPORT

Date of	Inspection: 07/12/2020 District: January		
Division: January Company			
Name of the Road: Sikandra PMASY Road to Bishanpur			
Scheme	Programme: MAINTENANCE	42	
Packag	12 L W 114 2019 WE 123 WORD IN 110!! 1) LIGHT IN CO	107	
	Ongoing/Completed/Under Maintenance	101	
	s a case of: New Connectivity/Up gradation/ Maintenance		
SI No.		Remarks	
1.	Pavement		
a)	Road Junction condition	S/U 🦳	52
b)	Condition of Surfacing	S/U	1
c)	Riding Quality	S/U	corgoing
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No A	-A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N	4
g)	Compaction of flank/slope & raincuts if any	Yes/No	1
2.	Cross Draininge		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U M	me has not be
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	10 done
c)	Condition of railings/slab/approach for Bridges	S/SRI/U y	Vin
3.	Road English		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No/	
4.	Compliance History		
a)	Status of ATR's & any others	N.X)	
Overall	Rating :	'N.A.	_
	Satisfactory (S)		٦
	Satisfactory but requires Improvement (SRI)		4
	Unsatisfactory (U)		-

Executive Me Temes

DESIGNATION: