## FIELD INSPECTION REPORT

Date of l	inspection: 67/12/2020 District: James		
Division: Janua Length (km): 0.841 KM			
Name of the Road: Commution of P.C. c Road in Minzagam Village			
	Programme: MAINTENANCE		1
Package No.: MR-N/19-2/Jame/10 Road Id No.: 2080 410 4017  Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Maintenance			
SINO	The state of the s		
A Charles Section 1	Parameters in Declecked.	Remarks	
1.	Pavement Control of the Control of t		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	ongoing
c)	Riding Quality	S/U	
d)	Road Camber	S/U ~	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N	P
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N	A
g)	Compaction of flank/slope & raincuts if any	Yes/No/	
	Cross Of sininge		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 4	ork has not been
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	don
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road-Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
<b>14</b> 1111	Compliance History		
a)	Status of ATR's & any others	N/A	3.
Overall	Rating: (Section 1997)	'N.A'	
	Satisfactory (S)  Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)		

NAME:

**DESIGNATION:** 

wastive Engineers on Right Williams

lumst.