## FIELD INSPECTION REPORT

Date of	Inspection: O	5/12/2020	District: Janua	
Division: Janu'			Length (km): 1.10 KM	
Name of	f the Road: Sik	kandra - Naw	ada Pucca road to Dhazar	pur Village Row
	Programme:	MAINTENANCE		
	No .: MR-N 11			38
Status of the Project: Ongoing/Completed/Under Me			and the second s	
AND STREET	CONTRACTOR SERVICES		/Up gradation/ Maintenance	
SI No	SALL STATE OF THE SECOND	Parameters t	o be checked	Remarks
	Pavement			
a)	Road Junction condition			_8/U
b)	Condition of Surfacing			~S/U
c)	Riding Quality			√S/U
<u>d)</u>	Road Camber			√\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NIA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NIA
g)	Compaction of flank/slope & raincuts if any			Yes/No
7.5	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			SISRIJU WOOK how been do
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.7	Road Farniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
<b>7 4</b> 1	Compliance History			
a)	Status of ATR's & any others			NIA

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	×

executive displaces on the control of the control o

NAME:

**DESIGNATION:**