

FIELD INSPECTION REPORT

Date of Inspection :- 3.12.20		District :- Khajuraho	
Division :- Khajuraho		Length (Km) :- 0122 Km	
Name of Road :- Const ⁿ of road from Burhawa to Bhikharighat (Missing Link)			
Scheme/Programme :- MR- New		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :-		<input checked="" type="checkbox"/> Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Upgradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a) -	Road Junction Condition		✓ S/U
b)	Condition of Surface		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		HA Yes/No ✓
f)	Constrution Joints provided or not (CC Pavement)		HA Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		HA S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		HA S/SRI/U
c)	Condition of railings/slab/approach for Bridges		HA S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained		✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)