

FIELD INSPECTION REPORT

Date of Inspection :	5/12/20	District:	Madhepura
Division :	Madhepura	Length (km):	4.80 km
Name of the Road:	Laxmipur Bagmati to Lalkhuria.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Agreement position.		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/I NA
b)	Condition of Surfacing	S/I NA
c)	Riding Quality	S/I N/A
d)	Road Camber	S/I NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI NA
c)	Condition of railings/slab/approach for Bridges	S/SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A

Birendra Kumar

NAME: JE, Kurnakland

Birend
5/12/20
(Signature)