

# FIELD INSPECTION REPORT

|                                                        |                                            |                        |
|--------------------------------------------------------|--------------------------------------------|------------------------|
| Date of Inspection : 07-12-20                          |                                            | District: madhepura    |
| Division : madhepura                                   |                                            | Length (km): 2.500 K.M |
| Name of the Road: P.W.D road Rajni to Gath milik road. |                                            |                        |
| Scheme/Programme:                                      |                                            | MAINTENANCE            |
| Package No.: 08                                        | ✓                                          | Road Id No.:           |
| Status of the Project:                                 | Ongoing/Completed/Under Maintenance ✓      |                        |
| Work is a case of:                                     | New Connectivity/Up gradation/ Maintenance |                        |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      | Not started |
| a)      | Road Junction condition                                                                                              | S/U         |
| b)      | Condition of Surfacing                                                                                               | S/U         |
| c)      | Riding Quality                                                                                                       | S/U         |
| d)      | Road Camber                                                                                                          | S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No      |
| 2.      | <b>Cross Drainage</b>                                                                                                | Not started |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U     |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U     |
| 3.      | <b>Road Furniture</b>                                                                                                | Not started |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No      |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of ATR's & any others                                                                                         |             |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

N.A

*N Kumar*  
07-12-20  
(Signature)

NAME: NARESH KUMAR

J.E