

FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	Madhepura
Division :	Madhepura	Length (km):	2.80 km
Name of the Road:	Const ⁿ of Road from Sukhasan via Chhama patti Sikashatti Road		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <u>Tender process</u>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance <u>✓</u>		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	N/A
b)	Condition of Surfacing	S/U	N/A
c)	Riding Quality	S/U	N/A
d)	Road Camber	S/U	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N/A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	N/A
4.	Compliance History		
a)	Status of ATR's & any others		N/A

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A

Birendra Kumar
J.E., Kumarkhola

Birend
4/12/20
(Signature)