

FIELD INSPECTION REPORT


Date of Inspection : 07/12/2020		District : Purnea	
Division : Purnea		Length (Km) : 2.950 KM	
Name of the Road : Babu dhar Rajheli to NBCC Road via Naya tola.			
Scheme/Programme :		Maintenance Mukhyamantri Gramin Path Amarakant	
Package No. : —		Road ID No. : —	
Status of the Project :		Ongoing/Completed/Under Maintenance (Work Just started)	
Work is a case of :		New Connectivity/Up gradation/Maintenance	

Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	S/U N.A.
b)	Condition of Surfacing	S/U N.A.
c)	Riding Quality	S/U N.A.
d)	Road Camber	S/U N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No N.A.
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U N.A.
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U N.A.
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	✓ Yes/No
4).	Compliance History	
a)	Status of ATR's & any others	N.A.

Note:- Work just started hence Satisfactory.

Overall Rating :	Satisfactory (S)	(S)
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	—

Name : Chandan Kumar Bhargava
 Designation : Assistant Engineer


 (Signature)
 07/12/2020