

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District : Purnea
Division : Purnea		Length (Km) : 3.740 KM
Name of the Road : Madhopara - Karanga Rice Mill NH-31 via Lalgarj.		
Scheme/Programme :	Maintenance Mukhya mentor Gramin path Anurakshen	
Package No. :	Road ID No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance <i>Work just started</i>	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	S/U <i>N.A.</i>
b)	Condition of Surfacing	S/U <i>N.A.</i>
c)	Riding Quality	S/U <i>N.A.</i>
d)	Road Camber	S/U <i>N.A.</i>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>N.A.</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>N.A.</i>
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No <i>N.A.</i>
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U <i>N.A.</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U <i>N.A.</i>
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U <i>N.A.</i>
3).	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No ☒
4).	Compliance History	
a)	Status of ATR's & any others	<i>N.A.</i>

Note:- work just started, hence Satisfactory.

Overall Rating :	Satisfactory (S)	(S)
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	—

Name : Chandan Kumar Bhargava
 Designation : Assistant Engineer

Chandran
 (Signature) 07/12/2020