

## FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District : Purnea
Division : Purnea		Length (Km) : 8.56
Name of the Road : Jangaili PWD Road to Singhia		
Scheme/Programme :	Maintenance 3054 MR (OLD)	
Package No. :	—	
Road ID No. :	—	
Status of the Project :	Ongoing/Completed/Under Maintenance out of Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	

Sl. No	Parameters to be Checked	Remarks
1).	<b>Pavement</b>	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No } N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No } N.A.
g)	Compaction of Flank/Slope & Raincuts if any	Yes/No ✓
2).	<b>Cross Drainage</b>	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U ✓
c)	Condition of Railings/Slab/Approach for Bridges	S/SRI/U ✓
3).	<b>Road Furniture</b>	
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained	Yes/No ✓
4).	<b>Compliance History</b>	
a)	Status of ATR's & any others	N.A.

Overall Rating :	Satisfactory (S)	—
	Satisfactory but requires Improvement (SRI)	(S) —
	Unsatisfactory (U)	(U)

Name : Chandan Kumar Bhargava  
 Designation : Assistant Engineer

Chandan Kumar Bhargava  
 07/12/2020  
 (Signature)