

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District : Purnea	
Division : Purnea		Length (Km) : 3.310 KM	
Name of the Road : Kishampur Pucca road to Bagalbari ghat via Durgasthan Barhiyabari Mushakheri tola.			
Scheme/Programme :		Maintenance Mukhyamantri Gramin Path Anurakshan	
Package No. : —		Road ID No. : —	
Status of the Project :		Ongoing/Completed/Under Maintenance (Work just started)	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
SL No	Parameters to be Checked		Remarks
1).	Pavement		
a)	Road Junction condition		S/U N.A.
b)	Condition of Surfacing		S/U N.A.
c)	Riding Quality		S/U N.A.
d)	Road Camber		S/U N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N.A.
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No N.A.
2).	Cross Drainage		
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U N.A.
c)	Condition of Railings/Slab/Approach for Bridges		S/SRI/U N.A.
3).	Road Furniture		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained		Yes/No
4).	Compliance History		
a)	Status of ATR's & any others		N.A.

Note:- Work just started, Hence Satisfactory.

Overall Rating :	Satisfactory (S)	(S)
	Satisfactory but requires Improvement (SRI)	—
	Unsatisfactory (U)	—

Name : Chandan Kumar Bhargava
 Designation : Assistant Engineer

Chandan Kumar Bhargava
 07/12/2020
 (Signature)