	FIELD INSPECTION REPORT	
	DISTRICT: PUT	nas.
DATE OF INSPECTION:	06/12/ DT	
DIVISION:	DHAMPHHA	
NAME OF THE ROAD:	PIELD INSPECTION REPORT DISTRICT: PUTALO. DIAMPHA LENGTH: 1. 200/CM Afthicopin to gridhe portini Ruperuo; Road. MAINTENANCE ROAD ID No.: ONGOING/COMPLETED/UNDER MAINTENANCE NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SCHEME/PROGRAMME:		
PACKAGE No:		
TATUS OF THE PROJECT:		
WORK IS A CASE OF:	PARAMETERS TO BE CHECKED	REMARKS
SL.NO		
11	PAVEMENT	
Α	ROAD JUNCTION CONDITION	5
8	CONDITION FO SURFACING	5
С	RIDING QUALITY	
D	ROAD CAMBER	2
	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	S
E	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N·V
F	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	5
<u> </u>	CROSS DRAINAGE	
	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS	N·A
A	PAINTING	N· A
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	
С	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N. A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	\$
<u> </u>	COMPLIANCE HISTORY	

OVERALL RATING

SATISFACTORY(S)	2
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	_
UNSATISFACTORY(U)	
engruer-	516NATURE 2020

NAME: Kamal Naryan shama. DESIGNATION: Pur'or imgruer.

STATUS OF ATR"5 & ANY OTHERS

Scanned by CamScanner

NO AM ATR