| | FIELD INSPECTION REPORT | |
|------------------------|---|------------|
| DATE OF INSPECTION: | 06/12/2070 DISTRICT: PURMER | |
| DIVISION: | DHAMDAHA LENGTH: 2-3601cm | |
| NAME OF THE ROAD: | DHAMDAHA LENGTH: 2-3601cm Tos Alcharla. to Bestingfor | |
| SCHEME/PROGRAMME: | MAINTENANCE | |
| PACKAGE No: | ROAD ID No.: | |
| STATUS OF THE PROJECT: | ONGOING/COMPLETED/UNDER MAINTENANCE | |
| WORK IS A CASE OF: | NEW CONNECTIVITY/UP GRADATION/MAINTENANCE | |
| SLNO | PARAMETERS TO BE CHECKED | REMARKS |
| 1 | PAVEMENT | |
| Α. | ROAD JUNCTION CONDITION | N.A |
| В | CONDITION FO SURFACING | N.A |
| C | RIDING QUALITY | N.A |
| D | ROAD CAMBER | N· A |
| Ę | WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT | N.A |
| F | CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT) | NA |
| G | COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY | N·A |
| 2 | CROSS DRAINAGE | |
| A | CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING | N.A |
| B | CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS | N.19 |
| C | CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES | N·A |
| 3 | ROAD FURNITURE | |
| А | WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED | 2 |
| 4 | COMPLIANCE HISTORY | |
| A | STATUS OF ATR"s & ANY OTHERS | NO ANY ATK |
| OVERALL RATING | | |
| | SATISFACTORY(S) | 2 |
| | SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U) | |

NAME: Kanne Naryan Shame.
DESIGNATION: Junior Conginer

-1

Scanned by CamScanner