

FIELD INSPECTION REPORT

DATE OF INSPECTION:	06/12/2020	DISTRICT:	PURNA
DIVISION:	DHAMDARA	LENGTH:	1.10km
NAME OF THE ROAD:	Askaiya to sholani		
SCHEME/PROGRAMME:	MAINTENANCE		
PACKAGE No:	ROAD ID No.:		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		

SLNO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	N.A
B	CONDITION OF SURFACING	N.A
C	RIDING QUALITY	N.A
D	ROAD CAMBER	N.A
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	N.A
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N.A
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	S
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	No any ATR

OVERALL RATING

SATISFACTORY(S)	S
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	-
UNSATISFACTORY(U)	-

NAME: Iyengar Jayan
DESIGNATION: J.E

Kumbar
6/12/2020
SIGNATURE