FIELD INSPECTION REPORT

Date of Inspection: 4 12 2020 District: Katihar			District : Katihar		
Division : Katihar Leng			Length (Km):		
Name of	the Road: Ko	asi To Harda jóhasy	ŢŪ		
Scheme/Programme: Maintenance			-		
Package	No.:		Road ID No. :		
Status of	the Project:	Ongoing/Completed/Under Maintenance			
Work is	a case of:	New Connectivity/Up gradation	on/Maintenance		
Sl. No		Parameters to be Checked		Remarks	
1).	Pavement				
a)	Road Junction condition			S/U NA	
b)	Condition of Surfacing			S/U NA	
c)	Riding Quality			S/U NA	
d)	Road Camber			S/U N/A	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA	
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No NA	
2).	Cross Drainage				
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U NA	
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U NA	
3).	Road Furniture				
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No NA	
4).	Compliance History				
a)	Status of ATR's &	any others			

Overall Rating

Satisfactory (S)					
Satisfactory but requires Improvement (SRI)					
Unsatisfactory (U)					
Status: Construction Under DMUSY phouse IT					

Name: Dilip Lumar

Degisnation: 7.E

RWD, Works Division, Katihar

(Signature)