FIELD INSPECTION REPORT

Date of Inspection: 4/12/2020			District : Katihar	District : Katihar		
Division : Katihar			Length (Km):	Length (Km):		
Name of	the Road: 100 a	si To Horda	NEA			
Scheme/Programme : Maintenance						
Package No.:			Road ID No. :			
Status of	the Project:	Ongoing/Completed/U	nder Maintenance			
Work is a	a case of:	New Connectivity/Up	gradation/Maintenance			
Sl. No	Parameters to be Ch		be Checked	Remarks		
1).	Pavement					
a)	Road Junction condition			S/U NA		
b)	Condition of Surfacing			S/U NA		
c)	Riding Quality			S/U NA		
d)	Road Camber			S/U NA		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NA		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No NA			
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No NA		
2).	Cross Drainage					
a)	Condition of Head walls in Hume Pipe Culverts including its painting			S/SRI/U NA		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U NA		
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U NA		
3).	Road Furniture			the same and the s		
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No NA		
4).	Compliance Hist	tory		<u> </u>		
a)	Status of ATR's &	k any others	4.0			

Overall Rating

Satisfactor		
Satisfactor	y but requires Improvement (SRI)	
Unsatisfact	ory (U)	
Status :	Construction Under by UISY	Shower II

Degisnation: Degisnation: 7, E RWD, Works Division, Katihar