FIELD INSPECTION REPORT

Date of Inspection: 3 12 2620			District : Katihar	District : Katihar			
Division	: Katihar		Length (Km): 1.30 KM	Length (Km): 1.30 KM			
Name of	fthe Road: 137	atwara pitch	Road to Khom'a Sadalpus	Road			
Scheme/	Programme:	Maintenance					
Package	No.:		Road ID No.: 2110 560	2013			
Status of	f the Project:	Ongoing/Completed/Under Maintenance					
Work is	a case of:	New Connectivity/Up	gradation/Maintenance				
Sl. No		Parameters 1	to be Checked	Remarks			
1).	Pavement						
a)	Road Junction condition			S/U	NA		
b)	Condition of Surfacing			S/U	NA		
c)	Riding Quality		S/U	NA			
d)	Road Camber			S/U	NA		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	NA		
g)	Compaction of Flank/Slope & Raincuts if any			Yes/No	NA		
2).	Cross Drainage				131		
a)	Condition of Head walls in Hume Pipe Culverts including its painting S/SRI/U N			NA			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.			S/SRI/U			
c)	Condition of Railings/Slab/Approach for Bridges			S/SRI/U			
3).	Road Furniture						
a)	Whether sign boards/Informatory/Cautionary Board/km & 200 m stones/Pavement road markings are provided and maintained			Yes/No	NA		
4).	Compliance History						
a)	Status of ATR's &	k any others					

Overall Rating

Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Status: In Timolor pricepss Under N	Mp-2018

Name: Dilip kumur Degisnation: JE

RWD, Works Division, Katihar