

FIELD INSPECTION REPORT

Date of Inspection :	05-12-2020	District:	Araria
Division :	Araria	Length (km):	0.980
Name of the Road:	Bachaneta to pahansi.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	91206008088
Status of the Project:	Ongoing/Completed/Under Maintenance <i>out of maintenance</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	N/A	S/U
b)	Condition of Surfacing	N/A	S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A

Note:- Out of five years maintenance.

NAME:

prince kr. kr. kr.
J.E

[Signature]
05.12.2020
AE.

Ranjeet kr mandal

(Signature)

[Signature]
05/12/2020