Date of Inspection:			District: Angrica.	
Division: Assaria.			District: Analica.  Length (km): 9. ~	
Name of			alchands semelori mate	looad.
Scheme/Programme: MAINTENA		MAINTENANCE		
Package No.:			Road Id No.: 21206008104	
Status of the Project: Ongoing/Cor		Ongoing/Completed/L	npleted/Under Maintenance	
Work is	a case of:	New Connectivity/Up	gradation/ Maintenance	
Sl. No.		Parameters to b	e checked	Remarks
71.	Pavement			terefore
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
	Whether free	from defects such	as visible cracks, exposed	200

4)	Koad Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
0	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3,	Road Eurniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	The control of the co	A STATE OF THE STATE OF
4.	Compliance History	

Overall Rating

Satisfactory (8)	MA
Satisfactory but requires Improvement (SRI)	MA
Unsatisfactory (U)	NIA

Note! - This soadistateen under pmasy-II

(Signature)

NAME: Frince 12 transcoin

Rayeed Ky Mandy