FIELD INSPECTION REPORT

Date of I	inspection: 0	District: Saram	9	
Division: Marhourer			Length (km): 3.880 km	
Name of	the Road: 10		itpur road in Beng c	
Scheme/Programme: MAINTENANCE		Shekhpurowia ghoghiya		
Package	No.: RM-SA	MAR-20-0002	Road Id No.: 31306201	027
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
SI. No.		Parameters to	be checked	Remarks
1.	Pavement			era de la companya de
a) -	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	ACCOUNTS OF THE PARTY OF THE PARTY.		James (Sec. 1)
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
b)	Condition of railings/slab/approach for Bridges			S/SRI/U
c)				
3.	Road Furnitu	Carlo de la carlo	Daviden & 200m	
a)	Whether sign	boards/informatory/ca nt road markings are p	nutionary Board/km & 200m rovided and maintained	Yes/No
1	Stollow - "	- 1 1		THE RESERVE OF THE PERSON OF T

Status of ATR's & any others

work not started

Overall Rating

4.

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	1

(Signature)

NAME: A SHUTOSH KUMAR RANJAN

Compliance History

DESIGNATION: P.E.