

FIELD INSPECTION REPORT

Date of Inspection : 5.12.2020	District: Saran
Division : RWD Madhaura	Length (km): 1.20 km
Name of the Road: Satjora to Pathvipur bet ⁿ to Harakhakari village	
Scheme/Programme: MAINTENANCE	M R- 30521
Package No.: RM/SA/MAR/19/0021	Road Id No.: 31306201033
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

work not started due to flood

Satisfactory (S)	0 X
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

5.12.2020
(Signature)

NAME: P. Mehra

DESIGNATION: CE