

# FIELD INSPECTION REPORT

Date of Inspection : 06-12-2020		District: Chapra
Division : Chapra-I		Length (km): 3.005 km
Name of the Road: Sontha - Mohzampur		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N 119-20 Chapra-I/10		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		✓ Not started
Work is a case of: New Connectivity/Up gradation/ Maintenance		✓

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S/SRI/U
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	Yes/No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

NAME:

DESIGNATION:

*(Signature)*  
06/12/2020