

FIELD INSPECTION REPORT Ekma

Date of Inspection : 06/12/2020	District: SARAN
Division : Chapra-2	Length (km): 0.410 km
Name of the Road: Chapra siwan mukhua Path to village Pandey Chapra Rajeshwar Pandey ke bahar Hite Hume Railway Phala jale wali	
Theme/Programme: MAINTENANCE	Path me PGC Sarak Nirman
Package No.: MR-N/19-20 Chapra-2/09	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

const. work has not been started

Gsingh
06/12/2020
(Signature) JE

ME:

SIGNATION: