

FIELD INSPECTION REPORT

Date of Inspection: 07-12-20	District: Sakas	
Division: R.N. 2 Chapra-2	Length (km): 3.490 km	
Name of the Road: Banipur to Baselpur		
Schema/Programme:	MAINTENANCE	
Package No.: R.N. 2/20 Chapra-2	Road Id No.:	
Status of the Project:	Cancelled/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up-gradation/ Maintenance	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Condition of Bank/slope & culverts if any	Yes/No
u)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work has not started

7.12.20
(Signature)
J.E.
Banipur

NAME:

DESIGNATION: