## FIELD INSPECTION REPORT Lablad buy

SARAN District: Date of Inspection: 04/12/2070 Length (km): 2.20 km chabra-2 Division: Name of the Road: Bhaija Ram Ki Dhori To Tawa Kali MAINTENANCE Scheme/Programme: Package No.: MR-N 19-20 chapra-421 Road Id No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of:

SI. No.	Parameters to be checked	Remarks
i.	Pavement	MATERIAL STATES
a)	Road Junction condition	S/U A
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	<b>北方。横</b>
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History work not started	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

work not started

NAME:

**DESIGNATION:**