

FIELD INSPECTION REPORT

Date of Inspection :	07-12-20	District :	Sikar
Division :	R.W. D. Chapra-2	Length (km) :	3.890 Km
Name of the Road :	BAITHI BAZAR TO SARAHAN		
Scheme/Programme :	MAINTENANCE		
Package No. :	DRN/19-20 Chapra-2	Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Upgradation/ Maintenance		

a)	Road Function condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Composition of flank/slope & culverts if any	Yes/No

a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U

a)	Whether sign boards/informatory/cautionary Board/km & 200m slance/Pavement road markings are provided and maintained	Yes/No
----	--	--------

a)	Status of ATR's & any others	
----	------------------------------	--

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

WORK HAS NOT STARTED.

ME :

SIGNATURE :

(Signature) H1212
JIE
Baniapur