

FIELD INSPECTION REPORT

Date of Inspection : 07-12-20	District: Sake
Division : R.H.D. Chapra-2	Length (km): 3.78 Km to 5.01 Km
Name of the Road: Dhobni Bazar to Chapra	
Scheme/Programme: MAINTENANCE	
Package No.: M/R-N/19-2004/42	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up-gradation/ Maintenance	
a) Road Junction condition	S/U
b) Condition of Surfacing	S/U
c) Riding Quality	S/U
d) Road Camber	S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
u) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) Condition of railings/slab/approach for Bridges	S/SRI/U
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
a) Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

Work has not started

(Signature)

7-12-20

B. K. Singh