FIELD INSPECTION REPORT EKMO

Date of Inspection : 6	7/12/2020	District: SARAN	
Division: chapte-2		Length (km): 1.062 km	
Name of the Road:	anumangani	To Teliadih	
Scheme/Programme:	ne of the Road: Hanumangani To Teliadih eme/Programme: MAINTENANCE		
Package No.: MR-NI			
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	S/U		
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4	Compliance History	Sanday.		
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

const. wirk has not been storted

(Signature)

NAME:

DESIGNATION: