## FIELD INSPECTION REPORT

Date o	f Inspection: 07 12 2021 District: Charas (Sax	an
Division: Chapse-1 Length (km): 0.526		
	of the Road: KANDE CE VLED-schie Per	1.
Scheme/Programme: MAINTENANCE 30th m/2		
Package No.:  Status of the Project: \Quad Quad Quad Quad Quad Quad Quad Quad		
	o de la condiciona de l	
1	The Connectivity of graduation Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	STU
d)	Road Camber	₩87Ú
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	\Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S(SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/GRI/U
c)	Condition of railings/slab/approach for Bridges	SASRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No~
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

:

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

02/12/10W

(Signature)

NAME:

**DESIGNATION:**