FIELD INSPECTION REPORT

	4.12.20	District: SARAN		
Division: MARHOR	A	Length (km): 1.840 K.M		
Name of the Road: Los-7 to DHAPAMPUR				
Scheme/Programme:	MAINTENANCE			
Package No.: Rm/36	VMAR/19/0016	Road Id No.: 31306402037		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing Riding Quality Road Camber Whether free from defeate such as visible gracks, exposed	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	s/sri/u
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No:

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI) SRI

Unsatisfactory (U)

(Signature)

Asil Is chouly NAME: 4.12.20

DESIGNATION:

P