

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	SARAN.
Division :	RWD Marhaura	Length (km):	2.60 km.
Name of the Road:	Tehti Bazar to Babar More kote huc trahad Ray Kehouse ^{felti.}		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31306508012
Status of the Project:	Ongoing/Completed/Under Maintenance ^{complete. out of 5yr.}		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA.
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA.
4.	Compliance History	
a)	Status of ATR's & any others	NA.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

work complete before 5yr. hence free from Maintenance

Art K. Chadda

NAME:

DESIGNATION:

PC

cu
dep
4/12/20
AR

(Signature)