## FIELD INSPECTION REPORT

Date of Inspection:	5.12.2020	District:	Saran	
Division: Madh	agra	Length (km):	1.70	len
		4 Se Turki	Hanur	morn Monder
Scheme/Programme:	MAINTENANC	1		
Package No.:	I amount of the same of the sa	Road Id No.:	THE R PERSON NAMED IN COLUMN 2	508013.
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1. —	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

HA

NAME: P-metry

DESIGNATION: