

FIELD INSPECTION REPORT

① SDBC Yet To be done
② Msc is being done.

Date of Inspection :	4/12/2020	District:	Silwan
Division :	R&D SIWAN-01	Length (km):	3.180KM
Name of the Road:	NIZAMPUR TO DIHA		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U is Being done
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U is Being done
d)	Road Camber	✓ S/U is Being done
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No is being done
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U Yet to Be done
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U No provision
c)	Condition of railings/slab/approach for Bridges	S/SR/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No YES
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

Manoj Kumar

Secy
4/12/2020
(Signature)