FIELD INSPECTION REPORT

Date of Inspection :	4/12/2020	District: mulaffappur		
Division: MUZAFFA	FOUR WEST	Length (km): 2.450 NM		
Name of the Road: CHANNI SUHAGPUR TO PARSURAMPUR				
Scheme/Programme:	MAINTENANCE	(new meist - 2018)		
Package No.: Rm/mu/	mu2/19/0012	Road Id No.: 31502202094		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	A Company of the Comp
a)	Road Junction condition	,S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	ا/8عی
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	_S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	Alberta de
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	(15)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Shanker Kumos

DESIGNATION: 5.E.